## Diverse Spindle types like motorspindles, high-power electrospindles, doublespindles, A full set of workpiece clamping and positioning systems for all requirements 6 - up to 16 stations for different machine basis with » 3-axis and 4-axis operations with vertical U-axis. All standard machining-units are exchangeable they fit for any configuration you need. or horizontal clamping axis optimized mass to reduce » 5-axis operations (swiveling axes)\*. the transfer time. YOUR DEDICATED **HORIZONTAL AND MACHINING SOLUTION VERTICAL (UPPER AND LOWER) MACHINING** Fix fixtures **OPERATIONS** YOUR **APPLICATIONS** Configured for your specific needs such as: productivity, Rotating and indexing fixtures precision, stiffness, reconfigurability, size, cost, power... Freely combine the platform elements according to the Mikron MultiX rules and set up your LOADING / machining solution. UNLOADING BC- axis On request, easy reconfiguration Remove the unit support box (with machining units) and reposition with Unique: with very fast Standard: 3-axis highest repeatability due to a zero point Unique: Table with horizontal and exchangeable clamping pick and place 6-axis robot clamping system (patented concept). vertical clamping combined interface in workpiece-axis

**MACHINING UNITS** 

A set of diverse machining units in different sizes to serve all your

**FIXTURES** 

**SPINDLES** 

**ENCLOSURES** 

**TRANSFER** 

**TABLES** 

**MACHINE BASIS**